

## BUILDING SAFETY CERIFICATE

File No: 349

Dated: 20-03-2024

It is certified that the exiting building St. Francis School (name of the building or premises) at Rajasewaiya Khurd Pithora (Address) is having blocks/Floors as per below.

Detail of block In school	Block 1 (one)	Block 2 (Two)	Block 3 (Three)	Block 4 (Four)	Block 5 (Five)
No of Floor in the block	Ground + three				

The building is owned/occupied by ST.FRANCIS SCHOOL (Name of the institution) have complied with the building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D Pithora (Name and address of the department Govt.) On 20/03/2024 (Date of inspection) in the presence of G. Raja Shekhar (Sub Engg) (name and address of the Manger/ secretary or his representatives) and that the building/premises is fit for occupancy for running school with effect from 2024 March For a period of Thirty years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.

Issued on 20/03/2024 at Pithora By .....

Signature with Seal. [Signature] Sub Divisional Officer

Name P.W.D.(B&R) Sub Division Pithora(C.G.) Pooja Ram Sharma

Designation: Sub Divisional officer

Name & Address of Department/ office P.W.D.(B/R) Sub Division Pithora

G. Raja Shekhar  
Sub Engineer  
P.W.D.(B&R) Sub Div.  
Pithora(C.G.)

Rosamma  
MANAGER  
ST. FRANCIS SCHOOL  
RAJASEWAIYA KHURD  
PITHORA MAHASAMUND

Rajni  
PRINCIPAL  
ST. FRANCIS SCHOOL  
RAJA SEWAIYA KHURD  
PITHORA P.O. PIN - 493551  
DIST. - MAHASAMUND (C.G.)